



# **SLOFEC™**

## **“Sample” Pipe Inpection Report**




*innospection Ltd.*

Unit27 - WebbEllis IndustrialPark  
WoodsidePark-Rugby  
Warwickshire CV21 2NP  
United Kingdom  
Phone: +44 (0)01788547294  
Fax: +44 (0)01788547299



Howemoss Drive  
Kirkhill Industrial Estate  
Dyce-Aberdeen-AB210GL  
UnitedKingdom  
Phone +44 (0)1224358524  
Fax +44 (0)1224358510

[www.innospection.com](http://www.innospection.com)

Signal-displays with color-analysis-threshold



Colored C-Scan of Calibration Sample 16"x10mm



Remarks :

---



---



---



---



---

## Calibration Scan



Client : OIL COMPANY  
 Location : REFINERY  
 Subject : Oil Rundown Lines  
 Pipe Identif. : P-53

Section : 2

Date : July/Agust2000  
 K-No. : 105/00

SLOFEC™ - PipeScan Report





Remarks :

---



---



---



---



---




Client : OIL COMPANY  
 Location : REFINERY  
 Subject : Oil Run-down Lines  
 Pipe Identif. : P-53

**Section : 1**

Date : July/Agust 2000  
 K-No. : 105/00

**SLOFEC™ - PipeScan Report**





**Remarks :**

---



---



---



---



---

Client : **OILCOMPANY**  
 Location : **REFINERY**  
 Subject : **Oil Rundown Lines**  
 Pipe Identif. : **P-53**

**Section : 2**


Date : **July/Agust2000**  
 K-No. : **105/00**

Distance below Top of Steel (TOS)

2.000  
2.500  
3.000  
3.500  
4.000  
4.500  
5.000  
5.500  
5.685

**Pipe P-52**




CIRCUMFERENTIAL DIRECTION



Distance to GTF [meter]

13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34

**20" x 0.75" P-053**



Remarks :

---



---



---



---



---



Client : OILCOMPANY  
 Location : REFINERY  
 Subject : Oil Rundown Lines  
 Pipe Identif. : P-53

**Section : 3**

Date : July/Agust2000  
 K-No. : 105/00

**SLOFEC™ - PipeScan Report**





**Remarks :**

---



---



---



---



---

Client : **OILCOMPANY**  
 Location : **REFINERY**  
 Subject : **Oil Rundown Lines**  
 Pipe Identif. : **P-53**

**Section : 4**

Date : **July/Agust2000**  
 K-No. : **105/00**

**SLOFEC™ - PipeScan Report**

